April 15, 2006 PN14BP.U5126.01.9200 SECOR INTERNATIONAL INCORPORATED

Mr. Patrick Lei County of Los Angeles Department of Public Works 900 South Freemont Avenue Alhambra, California 91803-1331

SUBJECT:

First Quarter 2006 Site Status Report

ARCO Facility 05126 800 East Valley Boulevard San Gabriel, California

CLADPW Closure Permit #351768

Dear Mr. Lei:

Attached please find the First Quarter 2006 Status Report prepared by SECOR International Incorporated on behalf of Atlantic Richfield Company. Should you have any questions regarding the contents of this report, please contact either Mr. Eric Young at (714) 230-0317 or Dr. G. Cleve Solomon at (805) 230-1266.

Respectfully submitted.

SECOR International Incorporated

Prepared by:

Eric Young

Project Scientist

Approved by: hard. Solor

G. Cleve Solomon, PhD, PG 5122

Principal Geologist


Enclosure

CC: Mr. John Batchelder, Atlantic Richfield Company

April 15, 2006 PN14BP.U5126.01.9200

ATLANTIC RICHFIELD COMPANY QUARTERLY STATUS REPORT

Station No.: 05126	Address: 800 East Valley	/ Boulevard, San Gabriel, CA
Atlantic Richfield Co. Environmental Project Manager /Phone No.:	Mr. John Batchelder/ (714) 670-3061	
Consulting Co./Contact/Phone No.:	SECOR / Mr. Eric Young/ (714) 230-0317	
SECOR Project No.:	14BP.U5126.01.9200	
Primary Agency/Regulatory ID No.:	Mr. Patrick Lei, Los Ángeles County Department of Public Works	
Other Agencies to Receive Copies:	None	
WORK PERFORMED THIS QUARTER [First of the continuation of the cont	d - 2006]: Report.	ust 27, 2003 directive.
Current Phase of Project:	Assessment	(Assmnt, Remed. etc.)
Frequency of Sampling:	Not Applicable	(Quarterly, etc.)
Frequency of Monitoring:	Not Applicable	(Monthly, etc.)
ls Liquid Phase Hydrocarbon Present On-site:	Unknown	(Yes/No)
Cumulative LPH Recovered to Date:	0	(gallons)
LPH Recovered This Quarter:	0	(gallons)
Bulk Soil Removed to Date:	Unknown	(cubic yards)
Bulk Soil Removed This Quarter:	0	(cubic yards)
Water Wells or Surface Waters within a 2000' Radius & Their Respective Directions:	Unknown	(Distance and Direction)
Current Remediation Techniques:	None	(SVES, LPH Removal, etc.)
Permits for Discharge:	Not Applicable	(NPDES, POTW, etc.)
Approximate Depth to Groundwater	>250 feet bgs	(Measured Feet)
Groundwater Gradient:	Unknown	(Direction)
	Unknown	(Magnitude)
Summary of Unusual Activity:	None	
Agency Directive Requirements:	Submit Workplan for Site Assessment	
ATTACHED: Site Location Map (Figure 1). Site Plan With Soil Sample Locat	ions (Figure 2).	



 \Box

Ш

BRI

GA

SAN

LEGEND:

APPROXIMATE PROPERTY
BOUNDARY

P1
SOIL SAMPLE LOCATION

DESTROYED GROUNDWATER
WELL LOCATION

PRODUCT PIPING

0 20 40
APPROXIMATE SCALE IN FEET



PREPARED FOR:

ATLANTIC RICHFIELD COMPANY
FACILITY 5126

800 E. VALLEY BOULEVARD
SAN GABRIEL, CALIFORNIA

JOB NUMBER: DRAWN BY: 14BP.U5126.

G. KAYA J. LEV

SITE PLAN WITH SOIL SAMPLE LOCATIONS FIGURE:

APPROVED BY: DATE: E. YOUNG APRIL 2006

Q:\CADD-14\Active\ARCO\05126\1Q06\A5126-1Q06.dwg

A5126-1Q06(FIG.2).DWG